

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)

- 1 Name of the Officer : Nishanth Kavungapparambil (Assistant Engineer)
- 2 Period for which the certificate is issued : 2024-2025
- 3 Details of building inspected : RCC ROOF
1. GROUND FLOOR
2. FIRST FLOOR
3. SECOND FLOOR
- 4 Nature of defect if any :
- a) Foundation and Basement : Laterite in cement mortar -1:6 for walls
- b) Superstructure : No defects noticed
- c) Doors and Windows : do
- d) Wood work wrought and put up : do
- e) Roof : do
- f) Flooring : do
- g) Miscellaneous (crack etc) : do
- 5 Any major defects noticed which will Render the building unsafe in any manner : Nil
- 6 Whether maintenance works have been Done properly : Yes
- 7 Whether the structure is sound or not For conducting classess : The structure is sound for conducting classess under normal weather and wind condition.
- 8 Any other remarks : Nil

- Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the **SILVERMOUNT INTERNATIONAL SCHOOL** was inspected by me on 28 /05/2024 and found to be fit to conduct classes for the period 2024-25 for the reason stated above.

Place : Perinthalmanna

Date 30/05.2024




Signature

Designation

VISHANTH KAVUNGAPARAMBIL
Assistant Engineer
Perinthalmanna Municipality
Ph:04933- 232363